



**EYEMOUTH HARBOUR**  
**LOCAL NOTICE TO MARINERS No. 8 of 2017**  
**Safe operation of vessels.**

Date of Issue: 29<sup>th</sup> November 2017

1. Mariners are hereby advised that the North Cardinal buoy marking the Hurkar Rocks is out of position. It is currently in the East Channel and is still lit.
2. The correct position of this buoy is 55° 52'.78N. 02° 05'.24W
3. Mariners should aware that this buoy is out of position and disregard it as a navigation mark until further notice.

**By order of the Harbour Master**

Richard Lawton  
Eyemouth Harbour Trust