



EYEMOUTH HARBOUR
LOCAL NOTICE TO MARINERS No. 14 of 2019
Inner Entrance port lateral mark .

Date of Issue: 17th September 2019

1. Mariners are advised that the port lateral light, Inner Entrance, is extinguished. The port mark structure is damaged but remains in position.
2. The starboard mark remains in position and lit
3. Mariners are advised to take extra care when navigating this part of the harbour.

By order of the Harbour Master

Richard Lawton
Eyemouth Harbour Trust