



EYEMOUTH HARBOUR

LOCAL NOTICE TO MARINERS No.12 of 2021

Updated North Cardinal Buoy & East Breakwater Light

Date of issue: 15/12/2021

1. Mariners are hereby advised that the North Cardinal buoy has been temporarily removed due to storm damage. We aim to have the North Cardinal back in position and lit in the coming weeks.
2. The correct position of this buoy is 55° 52'.78N. 02° 05'.24W
3. East Breakwater Lt No. 2841 has been repaired and working.

If further information regarding this notice is required then please contact Brendan Bates, Harbour Master on Tel: 018907 50223 / 07885 742505 email: harbourmaster@eyemouth-harbour.co.uk

By order of the Harbour Master

Brendan Bates
Eyemouth Harbour Trust