



## EYEMOUTH HARBOUR

### LOCAL NOTICE TO MARINERS No.10 of 2021

#### North Cardinal Buoy & East Breakwater Light

**Date of issue: 01/12/2021**

1. Mariners are hereby advised that the North Cardinal buoy marking the Hurkar Rocks is out of position and extinguished.
2. The correct position of this buoy is 55° 52'.78N. 02° 05'.24W
3. East Breakwater Lt No. 2841 is extinguished. Take special care when approaching Eyemouth from seaward.

**If further information regarding this notice is required then please contact Brendan Bates, Harbour Master on Tel: 018907 50223 / 07885 742505 email: [harbourmaster@eyemouth-harbour.co.uk](mailto:harbourmaster@eyemouth-harbour.co.uk)**

**By order of the Harbour Master**

Brendan Bates  
Eyemouth Harbour Trust