



EYEMOUTH HARBOUR
LOCAL NOTICE TO MARINERS No. 7 of 2017
Safe operation of vessels.

Date of Issue: 23rd November 2017

1. Mariners are hereby advised that the inner port-hand navigation mark in Eyemouth Harbour Entrance has been temporarily removed and the lamp (Red q.fl.) extinguished.
2. The position of this mark is the Entrance channel training wall/ South end of Fuel Jetty (55°52.408' N, 02°5.211'W) The Inner starboard-hand light (Grn.q.fl.) at the opposite side of the channel remains in operation.
3. Mariners are advised to take care transiting this part of the harbour.

By order of the Harbour Master

Richard Lawton
Eyemouth Harbour Trust