



## **EYEMOUTH HARBOUR**

### **LOCAL NOTICE TO MARINERS No. 11 of 2017**

#### **Safe operation of vessels: Cardinal Buoy and Port-hand mark replaced.**

Date of Issue: 4<sup>th</sup> December 2017

1. Mariners are hereby advised that the North Cardinal buoy marking the Hurkar Rocks, Eyemouth Bay has been restored to charted position.
2. The Inner port-hand navigation mark in Eyemouth harbour entrance has been restored.
3. This supersedes LNtM No.7 and LNtM No.8 of 2017

**By order of the Harbour Master**

Richard Lawton  
Eyemouth Harbour Trust