



**EYEMOUTH HARBOUR
LOCAL NOTICE TO MARINERS No. 2 of 2018
Cardinal Buoy out of operation.**

Date of Issue: 12th March 2018

1. Mariners are hereby advised that the North Cardinal buoy marking the Hurkar Rocks is out of operation.
2. The correct position of this buoy is 55° 52'.78N. 02° 05'.24W

By order of the Harbour Master

Richard Lawton
Eyemouth Harbour Trust