



EYEMOUTH HARBOUR

LOCAL NOTICE TO MARINERS No. 4 of 2018

Safe operation of vessels: Cardinal Buoy replaced.

Date of Issue: 8th April 2018

1. Mariners are hereby advised that the North Cardinal buoy marking the Hurkar Rocks, Eyemouth Bay has been replaced, but remains unlit.
2. The lamp is to be restored at the earliest opportunity and mariners will be informed.
3. The position of the buoy is as charted 55° 52'.78N. 02° 05'.24W

By order of the Harbour Master

Richard Lawton
Eyemouth Harbour Trust