



EYEMOUTH HARBOUR
LOCAL NOTICE TO MARINERS No. 8 of 2018
Safe operation of vessels.

Date of Issue: 13th December 2018

1. Mariners are hereby advised that the starboard-hand lateral navigation light (Grn.q.fl.) in Eyemouth Harbour inner entrance has been extinguished.
2. The position of this mark is (55°52.408' N, 02°5.231'W). The Inner port-hand light (Red.q.fl.) at the opposite side of the channel remains in operation.
3. Mariners are advised to take care transiting this part of the harbour.

By order of the Harbour Master

Richard Lawton
Eyemouth Harbour Trust