



**EYEMOUTH HARBOUR
LOCAL NOTICE TO MARINERS No. 1 of 2019
Cardinal Buoy out of operation.**

Date of Issue: 17th January 2019

1. Mariners are hereby advised that the North Cardinal buoy marking the Hurkar Rocks is off station and out of operation.
2. The correct position of this buoy is 55° 52'.78N. 02° 05'.24W

By order of the Harbour Master

Richard Lawton
Eyemouth Harbour Trust