



**EYEMOUTH HARBOUR  
LOCAL NOTICE TO MARINERS No. 3 of 2019  
Cardinal Buoy restored.**

Date of Issue: 22<sup>nd</sup> January 2019

1. Mariners are hereby advised that the North Cardinal buoy marking the Hurkar Rocks has been restored.
2. The position of this buoy is 55° 52'.78N. 02° 05'.24W

**By order of the Harbour Master**

Richard Lawton  
Eyemouth Harbour Trust