



**EYEMOUTH HARBOUR**  
**LOCAL NOTICE TO MARINERS No. 4 of 2019**  
**Starboard Lateral mark restored.**

Date of Issue: 22<sup>nd</sup> January 2019

1. Mariners are hereby advised that the lamp on the Starboard Lateral mark, inner entrance, has been restored.
2. The Port lateral mark has been damaged and remains unlit and out of operation.
3. Mariners are warned to take care near the Fuel jetty training wall as parts of the port mark structure remain in place below the half tide level.

**By order of the Harbour Master**

Richard Lawton  
Eyemouth Harbour Trust