



**EYEMOUTH HARBOUR
LOCAL NOTICE TO MARINERS No.6 of 2022**

**North Cardinal Buoy Eyemouth - Unlit and Submerged at High Water
Date of Issue: 13th Sep 2022**

Mariners are hereby advised that there are issues with the North Cardinal Buoy whereby the chain is pulling it under at high water. It is likely that it is not visible at all around high water, and the light on the buoy is not functioning at any time.

The Coastguard and Northern Lighthouse Board have been notified and we are working to arrange the required repairs a.s.a.p.

It has also been reported that creel markers are also encroaching on the navigation channel. Harbour users are reminded that any creel gear found near the channel will be removed immediately in accordance with the extant Local Notice to Mariners No. 2 of 2022 – Static Gear

<https://www.eyemouth-harbour.co.uk/notices-to-mariners/>

By order of the Harbour Master

Brendan Bates
Eyemouth Harbour Trust