



EYEMOUTH HARBOUR LOCAL NOTICE TO MARINERS No.8 of 2021

North Cardinal Buoy

Date of Issue: 23/09/2021

1. Mariners are hereby advised that the North Cardinal Buoy is currently out of position.
2. The North Cardinal buoy is currently 0.024 Nautical Miles Northwest from its charted position.
3. Mariners are advised to take special care when approaching and leaving the harbour.

By order of the Harbour Master

Brendan Bates
Eyemouth Harbour Trust