



EYEMOUTH HARBOUR
LOCAL NOTICE TO MARINERS No. 8 of 2019
Harbour Entrance Depths

Date of Issue: 15 March 2019

1. Mariners are advised that following severe silting depths in the entrance to the harbour are shallower than indicated on charts.
2. The most recent soundings show depths of 0.3m above datum in the Canyon and inner entrance channel.
3. Mariners are advised to take extra care and to plan entry and exit of the harbour according to tide and draft of vessel.
4. For current information on tide and conditions contact the Harbour Master on V.H.F. Ch.12 or Mob. 07885 742505 during office hours. Alternatively visit the Eyemouth Harbour Trust website (<http://www.eyemouth-harbour.co.uk/>) and Facebook page.

By order of the Harbour Master

Richard Lawton
Eyemouth Harbour Trust