

EYEMOUTH HARBOUR NOTICE OF NORTH CARDINAL MARKER

**Date of issue: 25 October 2023
No.9 of 2023**

Following Storm Babet, the cardinal marker has sustained some damage as follows:

1. Mariners are hereby advised that the North Cardinal Buoy is currently unlit and missing its markers.
2. Mariners are advised to take special care when approaching and leaving the harbour.

Northern Lighthouse Board and Coastguard have been notified of these issues and EHT will work to remediate as soon as practicable.

**If further information regarding this notice is required then please contact
Brendan Bates, Harbour Master on Tel: 018907 50223 / 07885 742505 email:
harbourmaster@eyemouth-harbour.co.uk**

By order of the Harbour Master

Brendan Bates
Eyemouth Harbour Trust