

EYEMOUTH HARBOUR LOCAL NOTICE TO MARINERS No.1 2024

Update on navigational matters

Date of issue: 19th March 2024

Entrance Channel:

The Entrance Channel East Side Navigation structure and light have been replaced, ensuring it is now functional and secure.

North Cardinal Bouy:

The North Cardinal Bouy remains unlit and out of position. The operations team is working on rectifying this issue as soon as possible.

- 1. Mariners are Hereby advised that the North Cardinal Buoy is currently unlit and missing its markers.
- 2. Mariners are advised to take special care when approaching and leaving the harbour.

If further information regarding this notice is required then please contact Brendan Bates, Harbour Master on Tel: 018907 50223 / 07885 742505 email: <u>harbourmaster@eyemouth-harbour.co.uk</u>

By order of the Harbour Master

Brendan Bates Eyemouth Harbour Trust